

# AIRWORTHINESS DIRECTIVE



AIR SAFETY DIVISION  
TUNGMAHAMEK, BANGKOK 10120  
TEL. 2862917, 2860530

DEPARTMENT OF AVIATION  
THAILAND

DOA AD. NO. 35/2538

The Department of Aviation has classified compliance with the document specified below as mandatory for aircraft operated on the Thai Register of Civil Aircraft with consideration of the prescribed effective date and special conditions.

EFFECTIVE DATE : JANUARY 1, 1996

APPLIES TO : ALL McCAULEY & HARTZELL VARIABLE PITCH PROPELLERS

DOCUMENT IDENTIFICATION : NONE

ISSUED BY : D.O.A. (THAILAND)

SPECIAL CONDITIONS : NONE

SUBJECT : TIME BETWEEN OVERHAUL

ALL McCAULEY & HARTZELL VARIABLE PITCH PROPELLERS, ACCOMPLISH

AS THE FOLLOWING :

(A) THE PROPELLERS MUST BE OVERHAULED WITHIN THE OPERATING HOURS RECOMMENDED BY THE MANUFACTURER OR WITHIN 7.5 YEARS CALENDER TIME, WHICHEVER COMES FIRST.

(B) ALL LIFE LIMITS PARTS MUST BE REPLACED AS SPECIFIED IN MAINTENANCE MANUALS.

THIS AIRWORTHINESS DIRECTIVE BECOMES EFFECTIVE ON JANUARY 1, 1996.

(MR. VICHAI PRATEEPPRECHA)

FOR DIRECTOR OF AIR SAFETY DIVISION

DATE OF ISSUE : DECEMBER 28, 1994

NO. 0405/3312