

## CAAT Ramp Inspection under COVID-19 influence

The Civil Aviation Authority of Thailand has conducted a Ramp Inspection of foreign operators flying from/to the Kingdom of Thailand on the basis of Chicago convention article 16.

To avoid COVID-19 infection, the ramp inspection procedure has changed temporarily as below.

- Ramp inspectors will conduct ramp inspection at Passenger Boarding Bridge (PBB) and outside the aircraft. (Essential cases are excepted.)
- Ramp inspectors will require each inspection item, then please show the items at PBB or outside of aircraft (if it is portable).

*Note: If it is not portable please explain the reason. (ex. Installed EFB.)*

Additionally, CAAT ramp inspectors have personnel protective equipment (wearing a disposable mask, gloves as a minimum) and confirm their health conditions (no symptoms of infections) and their certificate of full-dose vaccination upon briefing.

In any case, if the flight crew finds COVID-19 reaction is positive within 2 weeks from the day of this Ramp Inspection, please contact below.

Foreign Air Operators Division, Flight Operations Standards Department

The Civil Aviation Authority of Thailand

Mr. Manop Hungkasee

Head of Foreign Air Operators Division

TEL : +66 2568 8800 ext. 4310

Email: [contact.faoc@caat.or.th](mailto:contact.faoc@caat.or.th)

We sincerely appreciate your understanding and cooperation in our activity to keep aviation safe.